# Korsnäs Improves Pulp Digester Process Efficiency and Reduces Maintenance Cost with Vortex Technology

## **RESULTS**

- Operating cost savings through process efficiency improvement
- Reduced maintenance cost
- Mitigated workers health and safety risk

## **APPLICATION**

White liquor flow measurement in a Kraft (Sulfate) pulp digester

## **CUSTOMER**

Paper mill in Sweden

# **CHALLENGE**

Korsnäs is one of the world's leading producers of virgin fiber-based packaging materials. They use the Sulfate or Kraft pulp-making process in their mills, which uses white liquor (sodium hydroxide and sodium sulfide dissolved in water) as primary cooking chemicals in the digester. The white liquor is added to the pulp in the impregnation zone of the digester where it is heated and circulated, cooking the pulp. The alkali to wood ratio is carefully controlled to deliver a target Kappa number, which indicates the residual lining content or "bleachability" of the wood stock. Reliable flow measurement is critical in accurately controlling the alkali to wood ratio which directly affects digester performance.

They previously used a differential pressure flowmeter to measure the white liquor flow. The solids and fibers in the liquor flow would frequently plug the ports of the differential pressure flowmeter which resulted in unpredictable flow reading errors and eventual complete loss of the measurement until the meter could be removed and cleaned. They also tried a magnetic flowmeter, normally effective in this type of application, but in this case the flow meter was occasionally subjected to significant vacuum, which would partially collapse the liner. This caused the meter to read a higher flow rate resulting in too little alkali input, reducing digester performance.

When the flow measurement was inaccurate, unreliable, or completely failed the mill could not accurately control the alkali to



"The Rosemount 8800 Vortex has been working reliably for over a year with no downtime for cleaning or repair."

**Peter Hallenberg**Project Leader Process Automation



For more information: www.rosemount.com



wood ratio. Charging with too much alkali resulted in over-pulping, reducing the amount of usable fiber or yield. Too little alkali results in under-pulping, forcing the mill to use more unrecoverable chemicals in bleaching to hit the desired Kappa target. This process inefficiency resulted in higher cost per ton of the final product since shutting down the process means delay in production and higher cost of start-up.

## SOLUTION

The mill solved this flow measurement challenge by choosing a different metering technology to measure white liquor flow in this application. The Rosemount 8800 Vortex flow meter was selected as it is not affected by the high liquor temperature, vacuum, coating, or suspended solids in the flow. Typically, vortex flow meters are not considered for this application as the fluid contains solids and fibers that would clog the crevices and ports common to traditional vortex flowmeters. The Rosemount 8800 Vortex unique design eliminates crevices and ports which can be clog with solids and fibers, impacting performance, and is balanced so it is not affected by vibrations in the pipes that are typical in the mill. The resulting flow measurement is accurate, stable, and reliable. Reliability of the flow measurement enabled the Kappa number control to be restored allowing optimum control of the process. The result is more consistent pulp quality at lower cost per ton of pulp. Further, the mill is able to save on maintenance cost for cleaning the failed flowmeter and reduce the personnel's exposure related to maintenance and manual operation.



Rosemount 8800 Vortex Flowmeter.

## RESOURCES

## **Emerson Process Management Pulp and Paper Industry**

http://www2.emersonprocess.com/en-US/plantweb/customerproven/Pages/ PulpPaper.aspx

## **Rosemount 8800 Series Vortex Flowmeter**

http://www2.emersonprocess.com/en-US/brands/rosemount/Flow/Vortex-Flowmeters/ Pages/index.aspx

The contents of this publication are presented for information purposes only, and while effort has been made to ensure their accuracy, they are not to be construed as warranties or guarantees, expressed or implied, regarding the products or services described herein or their use or applicability. All sales are governed by our terms and conditions, which can be found at www.rosemount.com/terms\_of\_sale. We reserve the right to modify or improve the designs or specifications of our products at any time without notice.

The Emerson logo is a trade mark and service mark of Emerson Electric Co. Rosemount and the Rosemount logotype are registered trademarks of Rosemount Inc. PlantWeb is a registered trademark of one of the Emerson Process Management group of companies. All other marks are the property of their respective owners. © 2013 Rosemount Inc. All rights reserved.

**Emerson Process Management** Rosemount Incorporated 8200 Market Boulevard Chanhassen, MN 55317 USA www.rosemount.com

Tel (USA) +1 800 522 6277 Tel (International) +1 (303) 527 5200 Fax +1 (303) 530 8459

**Emerson Process Management** Blegistrasse 23 P.O. Box 1046 CH 6341 Baar Switzerland Tel +41 (0) 41 768 6111 Fax +41 (0) 41 768 6300

Emerson FZE P.O. Box 17033 Jebel Ali Free Zone Dubai UAE Tel +971 4 811 8100 Fax +971 4 886 5465

**Emerson Process Management Asia Pacific Private Limited** 1 Pandan Crescent Singapore 128461 T (65) 6777 8211 F (65) 6777 0947 Enquiries@AP.EmersonProcess.com

**Emerson Process Management Latin America Multipark Office Center** 

Multipark Office Center Turrubares Building, 3rd & 4th floor Guachipelin de Escazu, Costa Rica T+(506) 2505-6962 international.mmicam@emersonprocess.com



For more information: www.rosemount.com

